



BOROUGH OF NAUGATUCK, CONNECTICUT

NORTH MAIN STREET SIPHON REPAIR AT FULLING MILL BROOK

MARCH 2015



SHEET INDEX	
SHEET NO.	SHEET TITLE
C-0	COVER SHEET
C-1	GENERAL NOTES AND DETAILS
C-2	SITE PLAN
C-3	EROSION AND SEDIMENTATION CONTROL PLAN
S-1	STRUCTURAL - GENERAL PLAN
S-2	STRUCTURAL - NORTH WALL DETAILS
S-3	STRUCTURAL - SOUTH WALL DETAILS
S-4	STRUCTURAL - MISCELLANEOUS DETAILS



PROJECT LOCATION

BOROUGH OF NAUGATUCK



CAD FILE: G:\Clients\Naugatuck CT\20140128.001A - Naugatuck - Siphon Repair\Drawings\Cover Sheet.Dgn LAYOUT: 2/23/2015 11:16:41 AM BY: raymond.culver
 PLOTTED: 1/16/2015 11:16:41 AM BY: raymond.culver

